



OLENE S. WALKER
Governor
GAYLE F. McKEACHNIE
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON
Division Director

Supervisor 1007

Inspection Report Minerals Regulatory Program Report Date: September 3, 2004

Mine Name: Blue Castle

Operator or Permittee Name:
GoldTerra

Permittee Mailing Address:

4088 E. Airport Rd., Box 783, Price, Utah 84501

Inspector(s): Paul Baker

Other Participants: None

Weather: Mostly clear, 90's

Permit Status: Inactive

Current Acreages:

Total Permitted (Bonded): 5

Total Disturbed: <1

Permit number: S/015/077

Inspection Date: June 30, 2004

Inspection Start Time: 1:55 PM

Inspection End Time: 2:05 PM

Site location/Area Inspected (i.e. Pit #):
Entire area

Surface Ownership: BLM

Mineral Ownership: BLM

Mineral Mined: Gold from clay

Type of Mine: Surface

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: June 30, 2004; Report Date: September 3, 2004
Page 2 of 2
S/015/077

Purpose of Inspection:

I was in the area and wanted to check the status of the site.

Inspection Summary:

2. Public Safety

Since I last visited this site, the operator has made a ramp out of the pit so a person or animal could get out if necessary (Photo 2).

13. Revegetation

There is no vegetation at all in undisturbed areas near the pit.


Directions to the site:

Starting at US 6 and 191, take the road that leads to Lila Canyon. At the corral, turn left on to a graveled road; and the mine is maybe a hundred yards down this road.

GPS data:

I did not take GPS data.

Inspector's Signature



Date: September 3, 2004

PBB:jb

cc: Dan Sheppard, Operator
Dean Nyffeler, BLM, Price FO

O:\M015-Emery\S0150077-BlueCastle\inspections\ins-06302004.doc

**ATTACHMENT
Photographs**

S/015/077, Blue Castle, GoldTerra

Inspection Dated: June 30, 2004; Report Dated: September 3, 2004




Photo 1. Sign with the excavated material in the background.



Photo 2. Panorama of the pit area. Since I last visited the site, the operator has made a ramp so a person or animal could get out.